

# TES-3092 DC/AC CLAMP METER



## FEATURES

- 3-1/2 Digital LCD, 2000 count.
- Pocket size.
- MAX hold / Data hold function.
- One touch DCA zero.



## SPECIFICATION

### DC Current

Range	Resolution	Accuracy	Overload protection
200A	0.1A	+/- ( 1.5%rdg + 2dgts)	700Arms
700A	1A		

### AC Current

Range	Resolution	Accuracy	Frequency Range	Overload protection
200A	0.1A	+/- ( 2%rdg + 4dgts)	50 / 60Hz	700Arms
700A	1A			

### DC Voltage (Auto Range)

Range	Resolution	Accuracy	Input Impedance	Overload protection
600V	1V	+/- (1%rdg + 1dgts)	1M Ω	600Vrms


### AC Voltage

Range	Resolution	Accuracy	Frequency Range	Input Impedance	Overload protection
600V	1V	+/- (1.5%rdg + 4dgts)	50 ~ 400Hz	1MΩ	600Vrms

### Ohms (Resistance)

Range	Resolution	Accuracy	Overload protection
2K Ω	1 Ω	+/- ( 1%rdg+ 1dgts)	600Vrms

## GENERAL SPECIFICATIONS

<b>LCD Display</b>	3-1/2 digits, (MAX 1999). OL for over-range indication.  for Low battery indication.
<b>Power Source</b>	One 9V battery. (006P or IEC6F22).
<b>Battery Life</b>	100hr approx.
<b>Operating/Storage Condition</b>	0 °C to 50 °C < 80%RH. -10 °C to 60 °C < 70%RH.
<b>Dimensions</b>	188(L) x 62.5(W) x 30.5(H)mm
<b>Weight</b>	Approx. 185 g
<b>Jaw Opening Diameter</b>	Cables 27.5 mm
<b>Accessories</b>	Instruction Manual ,Battery, Test Lead and Carrying Case.