

Substitution of Universal Sensor 071 for 082

Due to supply-chain disruptions, the wire used in the Universal Sensor 082 is temporarily unavailable. As a result, the Universal Sensor 071 has been substituted for the 082 in the packaging of several products. The 071 has the same sensing specifications as the 082 with the following differences:

- Cable length shortened to 12" (300 mm) versus 8' (2.4 m)
- Temperature of wire jacket increased to 255°F (125°C) versus 221°F (105°C)

The substitution has been applied to the following tekmar products:

- DHW Control 257
- Boiler Control 260, 261, 268, 274, 275, 284
- Mixing Control 360, 361
- Universal Reset Control 374
- House Control 400, 401, 402, 403, 406
- Universal Reset Module 422, 423
- Mixing Expansion Module 441, 444
- Snow Melting Control 654, 670, 680

Once the supply-chain has been restored, these products will resume being packaged with the Universal Sensor 082.